

Tracking Number 1696

FIELD DATA SHEET 1


Site Information:

Occupant: [REDACTED]	Interviewee:
Address: [REDACTED] IMA	
Phone No.: [REDACTED]	
Owner Name, Address, and Phone No. if Different Than Occupant: [REDACTED] 0 [REDACTED] 13 [REDACTED] Marrero LA 70072	

Site Description:

1) Description of property (circle): single home; duplex; business; school; daycare; church; vacant house; vacant lot; other _____
2) Problems accessing yards (circle): locked gate; gate; dogs; other _____ resolution: _____
3) Underground utilities installed by owner? (circle): no; water; gas; electric; cable TV; septic tank; other _____ Note location on site sketch.
4) Is any underground ACM present? (circle): yes; no; don't know If yes, note on site sketch. How deep? _____

Site Sketch:



Estimated Volume of ACM: \_\_\_\_\_

Comments: SACM behind front gate.

Date/Time of Interview: 2/17/98 1800

Access Granted (circle): yes no

Team Members: GD

**07-1696-510**

991095

011855



In DB  
4/13